



Quality Service



Quality Inspectors Ltd.

CURRENT AND PAST PROJECTS



Quality
Service

	Company Name	Project Details	Contracted
1	Geothermal Development Company	<ul style="list-style-type: none"> ▪ Rig Repairs and Inspection ▪ Straightening of I Beam, Welding of Pad Eyes and Inspection. 	June-2013
2	Geothermal Development Company	<ul style="list-style-type: none"> ▪ Inspection of Hosting & Lifting Systems ▪ NDT Inspection of Cranes, Fork Lifts, Hoist, Lifting Tackles, Chains, Belts, Air Receivers, Air Winches by Visual Testing ▪ Inspection using Section 64, 65, & 67 of ▪ Occupational Health and Safety Act by a Government Inspector. 	January-2013
3	Geothermal Development Company	<ul style="list-style-type: none"> ▪ Inspection of Drill Pipes, Bottom Hole Assembly (BHA), Casing Tubing, Handling tools, Top Drive, by Ultrasonic Testing, Magnetic Particle Testing, Penetrant Testing, Visual Testing and Electromagnetic Inspection. ▪ Straightening, Handbanding of Drill Pipes and Heavy Weight Drill Pipes. 	January-2013
4	Glaxosmithkline Ltd	Radiography of re-fabricated ammonia line butt joints.	March-2012
5	Uganda Breweries	Radiography on new Fridge Plant erected by GEAGrasso,Holland	March-2012
6	AyokiFabriconPvt Ltd	Radiography on 1 x 22 TPH Vinasse Fired Travelling Gate Boiler for new ethanol distillery plant	December-2011
7	Abe- Tec (Ea)	Radiography on 80MW Thermal Station for Thika Power Ltd	October-2011
8	AyokiFabricon	Radiography Testing for 1x 35 TPH Boiler at Transmara Sugar Project	October-2011
9	AyokiFabriconPvt (Ethiopia Branch)	Radiography Testing for 2 x 35 TPH Boiler welds at Finchaa Sugar Project.	September-2011
10	Kenya Shell Limited (Changamwe)	Corrosion / Thickness Measurement of 12 x 100 ton LPG Storage facility. 14" Fuel Hydrant System to Passenger and Cargo Aprons	July-2011
11	Konoike Construction	Radiography Testing for Kapsabet Water Supply Project	July-2011
12	Bamburi Cement Ltd	Ultrasonic Testing and Magnetic Particle Inspection (MPI)	April-2011

		of the structural integrity of Roller Shaft for Kiln No.2.	
13	Krone E. A. Ltd	Radiography Testing for New packaging plant at Uganda Breweries	February-2011
14	AyokiFabricon	Radiography Testing of 1 x 35 TPH boiler for Butali Sugar Company	December-2010
15	East Africa Spectre	RT on LPG Cylinders	October-2010
16	Kengen Olkaria 1	None Destructive Testing(NDT) of Turbine Rotor At Olkaria I Power Plant	July-2009
17	Richfield Engineering Ltd	Ultrasonic Testing of the structural integrity of a sugar mill shafts for Chemilil and Muhoroni Sugar companies.	April-2009
18	Magadi Soda Co Ltd	Ultrasonic Testing and Magnetic Particle Inspection (MPI) of structural integrity of Kiln gears and shaft.	September-2008
19	Kenya Breweries Ltd Nairobi	Radiography of 6" steam line for new packaging line	January-2008
20	Tricon International Ltd Kisumu-Kenya	Radiographic Inspection of New Marine Vessel at Kenya Railways Yard Kisumu-Kenya	January-2008
21	Warren Enterprises Ltd-Kenya	Radiography of Fire Water Tank welds at Kenol - Kobil Nairobi Joint Depot.	December-2007
22	AyokiFabricon (Pty) Ltd	Radiography of Retrofit-Boiler tubes during Annual shut down	December-2007
23	Halls Equitorial Ltd	Radiography of New Fridge Plant Piping and associated accessories at Kenya Breweries Ltd. Radiography of Boiler piping weldments at Kibos Sugar & Allied Ltd	November-2007
24	Empower Eng. Systems - India	Radiography of 14" Steam Pipes at Kakira Sugar Factory - Uganda	November-2007
25	Pan-Paper Ltd (Webuye) Kenya		September-2007
26	Unilever Tea Kenya Ltd.	N.D.T inspection of boilers and steam receivers for statutory inspection in Kericho and LimuruUTL factories.	May-2006
27	Boc Kenya Ltd	Revalidation of LPG tanks (various sites coutrywide) 100 Tanks	May-2006

28	Heavy Engineering Ltd	Radiographic inspection on 2.6 Km penstock for SonduMiri Project	November-2005
29	Magadi Soda Company	Radiographic Testing of a Turnkey Project in Magadi	June-2005
30	Kenya Petroleum Refineries Ltd	Ultrasonic testing corrosion mapping of piping among other plant related accessories.	June-2005
31	SonguMiri Kengen/Heavy Engineering/I.H.I.	Radiographic Testing of Penstock	June-2005
32	Kenya Breweries Ltd	Radiography work (New ammonia Plant)	June-2005
33	Richfield Engineering Ltd	Radiography Testing of Longitudinal and Butt weld for the Boiler Furnace Shell for M/S Crown Beverage Ltd, Uganda.	April-2005
34	Ingersoll – Rand (Pty) Ltd., Sa, For Uganda Breweries Ltd.	Radiography Testing of Butt welds of Cooling / Compressed Air Pipe work at Uganda Breweries Ltd.	April-2005
35	Trident Plumber	Radiography work at Kobil – hydrant pipe	March-2005
36	Uganda Breweries Ltd / Grasso International	Radiograph work on ammonia line	March-2005
37	Muhoroni Agrochemical	Radiographic testing of the reservoir tank	January-2005
38	Agro Chemical And Food Company Ltd	Ultrasonic Testing of the structural integrity of a molasses tank inclusive of the concrete foundation and related accessories	January-2005
39	Richfield Engineering Ltd	Radiography Testing of Rehabilitated Molasses Tank for M/S Agro – Chemical and Food Company	December-2004
40	Prashanth Projects Ltd	Radiography Testing of Butt welds on 2 No. Jet A 1 Storage Tanks and associated process piping for Kenya Pipeline Company (KPC) in Kisumu and Eldoret Depot	December-2004
41	Huppmann Engineering	Radiography Testing of Welder Test Pieces and Butt welds of associated pipe works in the Kenya Breweries Ltd Brew House extension and Supply of Dye Penetrant consumables.	December-2004
42	Richfield Engineering Ltd (Nairobi, Kenya)	Radiographic Testing or Longitudinal and Butt weld for the Boiler Furnace Shell for M/S Crown Beverage Ltd, Uganda	November-2004

43	Kenya Pipeline Company Limited	Welding inspection and NDT Tests of the Emergency design and installation of 16" diameter AGO, 12" diameter MSP and 12" diameter DPK white oil pipelines and associated accessories between Kipevu Oil Terminal jetty (KOT) and Kipevu Oil Storage Facility (KOSF), Mombasa	November-2004
44	Uganda Breweries Ltd	Welding Inspection and Radiography Testing of 100 % total weld of Manhole (s) Resealing of 2 No. Carbon Filters Tanks.	October-2004
45	Haco Industries Ltd (Nairobi, Kenya)	Radiography Testing of Butt welds and Dye penetrant inspection of fillet / socket welds of Chlorine Plant pipe work	October-2004
46	Pan African Paper Mills	Radiography Testing of Weld Joints for Recovery Boiler Retrofit Tubes	October-2004
47	Kenya Petroleum Refineries Ltd	On stream Pipeline and Valves Radiography Testing and related welded joints during 2004 Complex I Shut Down.	August-2004
48	Zakhem Construction Co. Ltd (Mombasa, Kenya)	Radiography Testing of Butt joints on 1.7 KM 12" Fuel Oil Pipe line, Phase II for M/S Kenya Petroleum Refineries Ltd.	August-2004
49	Kenya Pipeline Company (Kpc)	Radiography Testing of Installation of 16" Diameter AGO, 12" Diameter MSP and 12" DPK white oil pipeline between Kipevu Oil Terminal Jetty (KOT) and Kipevu Oil Storage Facility (KOSF) Mombasa.	August-2004
50	Kenya Petroleum Refineries Ltd	Corrosion Mapping of Petrochemical Vessels, Columns, Heat Exchangers, Separators and related Pipe works using Ultrasonic Inspection – Complex I shut down Year 2004	August-2004
51	Pencol Engineering Consultants For Kenya Pipeline Company Limited	Supply of NDT Inspection supervisory staff for the Installation of additional Jet A 1 storage tanks and associated facilities in – Welding / QA/QC Engineering at Kisumu and Eldoret depot of Kenya Pipeline Company limited.	July-2004
52	Kenya Petroleum Refineries Ltd	On stream Pipeline and Valves Radiography Testing and related welded joints	April-2004
53	Kenya Petroleum Refineries Ltd	Corrosion Mapping using Ultrasonic Testing of piping and other related plants accessories	April-2004
54	Bamburi Cement Ltd	Ultrasonic Testing and Magnetic Particle Inspection (MPI) of the structural integrity of Rocker Arm and Grinding Roller Shaft.	April-2004

55	East African Spectre	Radiography Testing of 100% weld length of LPG Cylinder	March-2004
56	Zakhem Construction Co Ltd / Kenya Pipelin Corporation.	Radiography Testing of oil pipeline butt welds and fire fighting water piping system line. Dye Penetrant Inspection of the fillet joints on the oil pipeline and fire fighting water piping system for construction of Kenya Pipeline Company (KPC) Pump Station (PS) 23, Morendat Project.	January-2004
57	Kenya Petroleum Refineries Ltd	Ultrasonic Thickness Measurements of Oil Storage Tanks, Columns and related pipe works.	January-2004
58	Tricon International	Radiography Testing of 100% T's" on the Deck, Side Shells and Bottom Plate of a Marine Vessel, MV Harambee in Kisumu Shipyard.	December-2003
59	Heavy Engineering Ltd	Radiography Testing of Welder Test Pieces	December-2003
60	Richfield Engineering Ltd	Radiography Testing of 100% weld length of a Side Draw Vacuum Receiver	December-2003
61	Richfield Engineering Ltd	Radiography Testing of 100% T's' and 10% Total Length of weld of 100T LPG Bullet Tank for M/S Kenya Shell	December-2003
62	Richfield Engineering Ltd / Kenya Pipeline Corporation	Radiography Testing of 100% total length of weld of a Drain Tank for M/S Kenya Pipeline Company- PS 23, Morendat	December-2003
63	Richfield Engineering Ltd (Nairobi, Kenya)	Radiography Testing of Welder Test Pieces	November-2003
64	KenGen Olkaria li Geothermal Power Project	Independent Testing Authority for KenGen client, Sinclair and Mertz Consultants and JFE/Marubeni/Zakhem Contractors for Contract OG 105 Steam Field Development. Covering over 20KM steam pipes ranging from 50 mm to 1050 mm in diameter. 100% Butt joints Gamma Radiography Inspection, welding procedure and welders' qualification. Over 7500 Joints were inspected.	November-2003
65	U B Engineering Co. Sumitomo	Radiographic Inspection on Crane girder welds for East African Portland Cement. Radiography Testing of welds for welder's qualification.	October-2003
66	Kobil (K) Ltd	Ultrasonic Plate thickness measurements on 10 Bulky Oil Storage Tanks	September-2003
67	Kenya Shell Ltd	Decommissioning of LPG Tanks and steaming internal and external by Ultrasonic & Magnetic Particle Inspection (MPI) and dye Penetrant, tests at Kenya Railways Central Workshop.	June-2003

68	Pan African Paper Mills	Radiography Testing of 100% of welded Joints on Prefabrication of High Pressure Pipe (Boiler)	May-2003
69	Kenya Petroleum Refineries Ltd	Ultrasonic Thickness Measurements of Oil Storage Tanks, Plant Accessories and related pipe works.	May-2003
70	H. Young And Company	Radiographic Inspection of Crane Girders	April-2003
71	Kenya Shell Ltd	<p>Ultrasonic thickness measurement and corrosion mapping of 1 No. LPG – 150 ton Tank at Nairobi Depot. Ultrasonic thickness measurements and corrosion mapping tanks i.e.</p> <ul style="list-style-type: none"> • Coast Province – 37 Tanks • Mt. Kenya Region – 47 Tanks • Nairobi Area – 44 Tanks • Western Region – 20 Tanks 	March-2003
72	Jfe / Zakhem Construction Co.	Radiography Testing of 5 No. Oil Storage Tanks and associated pipe work. Dye Penetrant Inspection on the Oil Storage Tank reinforcement ring and fillet welds. Vacuum Box Testing on the Oil Storage Tanks base plate Butt Weld and Fillet Welds for Kenya Pipeline Company (KPC) – KOSOF Upgrade Project, Mombasa.	February-2003
73	Shell Uganda Limited	Radiography Testing of welds for a installation of a new LPG Tank No. 2 and associated pipe work	October-2002
74	Presbyterian Church Of East Africa – Kikuyu Hospital	Ultrasonic Testing of Structural Integrity of a Bullet LPG Tank and Statutory Inspection covering Safety	October-2002
75	Tricon International	Radiography Testing of 100% T's" on the Deck, Side Shells and Bottom Plate of a Marine Vessel, MV Kenyatta in Kisumu Shipyard.	August-2002
76	Tricon International	100% Ultrasonic Testing of welded joints of a Marine Vessel, MV Kenyatta in Kisumu Shipyard.	August-2002
77	Kenya Breweries Ltd (Kbl)	Ultrasonic Testing of Structural integrity and thickness measurements of spent grains silo's No. 001 and 002	July-2002
78	Bamburi Cement	Ultrasonic Testing of structural integrity of a Cement Kiln, Rollers station and gear shaft.	June-2002
79	Kenya Petroleum Refineries Ltd	Ultrasonic Thickness measurements of Oil Storage Tanks, Plant Accessories and related pipe works.	April-2002


80	Kenya Petroleum Refineries Ltd	Ultrasonic Thickness measurements of CDU Overhead pipeline system	February-2002
81	Caltex Oil (K) Ltd	Interpretation of Industrial Radiographs	December-2001
82	U.D.V Kenya	Ultrasonic Thickness measurements and Visual inspection of 4 No. Bulk Storage Tanks.	December-2001
83	Zakhem Construction Co.	Radiography Testing of Welders Test Pieces	September-2001
84	Asp Company Limited	Radiography Testing of Butt welds of 900 No. Pipes	June-2001
85	Mitsubishi Heavy Industries (Nairobi, Kenya)	Magnetic Particle Inspection (MPI) on thermal power generation engine pistons	June-2001
86	U. B. Engineering Co. Sumitomo	NDT Inspection of Welds for Welder's qualification. Inspection welds by radiographic on Crane girder at Athi River Site.	January-2001
87	B.A.T. (Thika, Kenya)	NDT Inspection of 30 tons overhead crane	November-2000
88	Grandoug Ltd	100% external and internal corrosion inspection and condition assessment of 100 No. 1 ton. Chlorine liquid storage cylinders	October-2000
89	Sonic Technical Services (Uganda)	Ultrasonic Inspection of Rotor Shaft for fabrizor	October-2000
90	Spenco Services Ltd	Ultrasonic Inspection of Plate Girders for the bridge deck at Bukora Bridge Kasensero Road, Uganda	September-2000
91	Sonic Technical Services (Uganda)	Ultrasonic Testing and Surface inspection of GE type Locomotive	June-2000
92	Menegai Oil Refinery Ltd	Radiographic Testing of pipe welds on a high - pressure boiler system.	June-2000
93	Kenya Petroleum Refineries Ltd	Corrosion Mapping using Ultrasonic Testing of piping and other related plants accessories	June-2000
94	Mombasa Diesel Generating Power Project Co. Ltd	Ultrasonic Inspection of Hydro Plant thrust bearing plates for KenGenKipevu Power Station.	October-1999
95	Caltex Oil (K) Ltd	Ultrasonic Thickness Measurement and surface methods - Magnetic Particle Inspection (MPI) and Dye Penetrant on the internal surface of the Tank	July-1999

96	East African Gas / Kenya	Ultrasonic testing, Radiographic and visual Structural integrity assessment of 4No. tanks of 4000 m ³	April-1999
97	Magadi Soda Co. Ltd	Corrosion mapping of half a million gallon steel water tank.	February-1999
98	Impregilo – Salini	Owen-Falls Dam Project Uganda Ultrasonic inspection of welds on powerhouse superstructures.	October-1998
99	Kenya Shell Ltd	Ultrasonic thickness measurement and corrosion mapping of 1 No. LPG – 150 ton Tank at Nairobi Depot.	March-1998
100	Insteel Ltd	Ultrasonic inspection of weld and corrosion mapping of zinc galvanizing vessels.	March-1998
101	Central Glass Industries Ltd	Corrosion mapping by Ultrasonic Testing of a 50M high industrial chimney	February-1998
102	Uganda Breweries Ltd	Ultrasonic Testing of welds on Boiler tubes at UBL Plant	April-1997
103	Kenya Shell Ltd	Ultrasonic thickness measurement and corrosion mapping of 1 No. LPG – 150 ton Tank at Nairobi Depot.	March-1997
104	East Kenya Bottlers	Non Destructive testing of factory Boiler	November-1996
105	Bulleys Tanneries Ltd	2 No. Boilers Radiographic and Ultrasonic Inspection	March-1996
106	Firestone E.A (1969) Ltd	Ultrasonic Inspection of Roll mill for corrosion crack detection and defect sizing, and Radiography Testing on welds on Boiler Tubes.	March-1996
107	Larsen & Toubro / Magadi	Radiographic work for Magadi pure ash project.	June-1996
108	Bamburi Cement Ltd	Ultrasonic Testing and Magnetic Particle Inspection (MPI) on Cement Mill Grunion Inlet and Outlet	August 1996

Additional NDT Work Performed

Company	Project Details
Kenya Breweries Ltd	Inspection requirements survey Mombasa and Nairobi plants, covering plant & Equipment and fire protection system
Bulleys Tanneries Ltd.	Insurance Survey for plant and machinery covering fire protection system.
Royal Insurance Co. Ltd.	Magadi Rail train accident Inspection of 13 No. Hopper Wagons evaluation.

Skoda Export. (Czech Republic)	<p>Equipment commissioning surveillance. World Bank project for six public Kenyan Universities, Personnel training equipment consultant Appointed by Skoda of Greek republic for 6No. public University Laboratory Equipment</p> <p>U\$ 1.5 million project funded by World Bank</p> <ul style="list-style-type: none"> • Kenyatta University • Nairobi University • Egerton University • Moi University • Maseno University
DFID/British Council/ Kenya Bureau Of Standards	<p>ISO 17025 Laboratory Quality Management training for Kenya Bureau of Standards Laboratories:-</p> <ul style="list-style-type: none"> • Personnel training • Quality Manual development • Technical Audits • Preparation of United Kingdom Accreditation system (UKAS) assessment.
Cooperative Bank (K) Ltd	<p>Civil and Structural Consultant for design built rehabilitation project of the co-operative Bank after the Bomb Blast representing the Co-operative Bank of Kenya.</p>
Pencol Engineering Consultants	<p>Subcontract to Pencol engineering</p> <p>Consultants for consultancy work for Kenya Pipeline (KPC) Mombasa, KOSOF project covering provision of consultants in Civil, Mechanical, Electrical, Instrumental and Control and Welding Inspection in storage tanks and pipeline</p>
Pencol Engineering Consultants	<p>Subcontractors to Pencol Engineering Consultants for consultancy for work for Jet- A1 project in Kisumu and Eldoret covering Oil storage tanks and associated systems. Covering Civil, Mechanical, Welding, Instrumentation and Electrical services</p>
Kenya Pipeline Company Ltd.	<p>KOT – KOSF Product Pipeline Replacement Emergency Project. Provision of Civil, Mechanical, Electrical, Instrument & Control and Welding Inspection services for the project.</p>
Telkom Kenya Ltd / Lloyd Masika Ltd	<p>Consultancy work on corporate restructuring of Telkom Kenya Ltd with regard to valuation of Company assets.</p>



Quality Inspectors Ltd.

Head Office
Josem Trust Place (Bunyala Rd.)
P.O. Box 34284 00100 Nairobi.
Tel:254 020 2721376
Fax:254 020 2721389
Email:info@qil.co.ke

Jomo Kenyatta International Airport
& Inland Container Depot.
P.O. Box 34284 00100 Nairobi.
Tel:254 020 2721376
Fax:254 020 2721389
Email:www.qualityinspectors.net

Nakuru Blankets Center
Godown No. 3
P.O. Box 18358-00410
Nakuru, Kenya
Telephone: +254 20 2689166

Mombasa Radiology Office
Panji Building,3rd floor
Moi Avenue Rd
P.O. Box 34284 00100 Nairobi.
Tel:254 020 2326844

